

HAROLD BOOT COMPANY





PLEASE MEASURE BARE FOOTED & BARE LEGGED STANDING UP ON A FIRM SURFACE

1 CALF

2. HEIGHT

HEIGHT

MEASURE FROM 3 TO 2 WHICH IS ANKLE BONE TO KNEE BONE

CALF

AT POINT 1
BARE LEGGED
STANDING UP

3.ANKLE

LENGTH	CALF SIZE	LENGTH	CALF SIZE	LENGTH	CALF SIZE
14	13	15	13	16	14
14	14	15	14	16	15
14	15	15	15	16	16
		15	16		